



Roland SERVICE INFORMATION

NO.	100215-(2)
DATE	Oct. 13, 1984

PRODUCT AFFECTED: _____

TO SERVICE ENGINEERS:

SUBJECT

Supplemental Information related with
Service Information No.100215

The current OC-8 includes DCB Cable H146(Flat-Flat type) for OP-8. However, this cable cannot use for "OP-8M" (CV-DCB/MIDI Interface). Because OP-8M has only DCB and MIDI Connectors, not Flat Connector. So this time, we changed the accessory DCB Cable of OC-8 from DCB Cable H146 to DCB Cable H231 (Flat-Amphenol type) for connection with OP-8M.

H146(Flat-Flat)
OP-8 -----> JP-8(w/OC-8)

H231(Flat-Amphenol)
OP-8M -----> JP-8(w/OC-8)

10/13 RUS. US (Tsuruta), RCA, DK(10), Sweden, Norway
R.I.C. RWG RCM, Swiss, France, Spain,
Italy, Austria, BNIX, Mexico, New Zealand,
Finland, Greece, Sue Lee, Tom Lee,